



Certification Programs

1220 L Street, NW
Washington, DC 20005-4070
USA
Telephone 202-962-4791
Fax 202-682-8070
Email certification@api.org
www.api.org/certification

Facility ID #: 1787
Automatic Notification - Extension Letter

January 5, 2009

Tenaris Siat (Valentin Alsina Facility)
Guatemala 3400
Buenos Aires, Valentin Alsina 1822
Argentina

Attention: Claudio Rita

Re: License(s) 5CT-0281; 5L-0210

API's goal is to complete the renewal process to coincide with the expiration date of your license. However, the process has been delayed.

The expiration date of your current license(s) has been extended until April 02, 2009.

If your organization has not submitted the required documentation, please do so at this time. However, if your audit has not been scheduled and/or performed, an API auditor will contact you shortly. Please note that we will notify you of the results of all pending reviews within a few weeks.

Just as the demand for oil and natural gas has increased over the last several years, so has the call for monogrammed equipment and for API Certification. As a result, our processing times have increased considerably, but we are working very hard to keep up with new demands and we are taking all steps possible to reduce turnaround time.

API would like to thank you for your patience and cooperation during the licensing renewal process.

Regards,


API Certification Programs